




Magic Joint System Plus L

Straight joint with **cast gel**
Five-core spacer + screw connectors.




For COPPER cables	Cable formation and conductor cross sections (n° x mm ²)				Dimensions A x B (mm)
	2x	3x	4x	5x	
Product					
Magic Joint SP L6	1,5 - 6	1,5 - 6	1,5 - 6	1,5 - 6	180 x 50
Magic Joint SP L16	4 - 16	4 - 16	4 - 16	4 - 16	215 x 55
Magic Joint SP L25	4 - 25	4 - 25	4 - 25	4 - 25	215 x 65



Magic Joint System Plus Y

Y branch joint with **cast gel**
Five-core spacer + screw connectors.




For COPPER cables	Cable formation and conductor cross sections (n° x mm ²)								Dimensions A x B (mm)
	2x		3x		4x		5x		
Product	T	B	T	B	T	B	T	B	
Magic Joint SP Y6	1,5 - 6	1,5 - 4	1,5 - 6	1,5 - 4	1,5 - 6	1,5 - 4	1,5 - 6	1,5 - 4	180 x 90
Magic Joint SP Y16	4 - 16	1,5 - 4	4 - 16	1,5 - 4	4 - 16	1,5 - 4	4 - 16	1,5 - 4	220 x 105



Magic Joint System Plus T

T branch joint with **cast gel**
Five-core spacer + screw connectors.



For COPPER cables	Cable formation and conductor cross sections (n° x mm ²)						Dimensions A x B (mm)
	2x		3x		4x		
Product	T	B	T	B	T	B	
Magic Joint SP T35	6 - 35	1,5 - 10	6 - 35	1,5 - 10	6 - 35	1,5 - 10	305 x 155

- Joints insulated with **Magic Gel**
- Quick cross linking gel (only 10 minutes)
- Extremely adherent and tight sealing
- Non-toxic and no shelf life
- For 0.6/1 kV extruded cables

Operating temperature **90°**

Installation temperature:
-10°C / +45°C