




Magic Power Joint System Plus L

Straight joint with **cast gel**

Five-core spacer + screw connectors.




Product	Cable formation and conductor cross sections (n° x mm ²)				Dimensions A x B (mm)
	2x	3x	4x	5x	
Magic P Joint SP L6	1,5 - 6	1,5 - 6	1,5 - 6	1,5 - 6	180 x 50
Magic P Joint SP L16	4 - 16	4 - 16	4 - 16	4 - 16	215 x 55
Magic P Joint SP L25	4 - 25	4 - 25	4 - 25	4 - 25	215 x 65



Magic Power Joint System Plus Y

Y branch joint with **cast gel**

Five-core spacer + screw connectors.



Product	Cable formation and conductor cross sections (n° x mm ²)								Dimensions A x B (mm)
	2x		3x		4x		5x		
	T	B	T	B	T	B	T	B	
Magic P Joint SP Y6	1,5-6	1,5-4	1,5-6	1,5-4	1,5-6	1,5-4	1,5-6	1,5-4	180 x 90
Magic P Joint SP Y16	4-16	1,5-4	4-16	1,5-4	4-16	1,5-4	4-16	1,5-4	220 x 105


T: Through - B: Branch



Magic Power Joint System Plus T

T branch joint with **cast gel**

Four-core spacer + screw connectors.



Product	Cable formation and conductor cross sections (n° x mm ²)						Dimensions A x B (mm)
	2x		3x		4x		
	T	B	T	B	T	B	
Magic P Joint SP T35	6 - 35	1,5 - 10	6 - 35	1,5 - 10	6 - 35	1,5 - 10	305 x 155

T: Through - B: Branch



- Joints insulated with **Magic Power Gel**, the only agglomerating gel
- Re-enterable, removable, inspectable
- For installations even in harsh conditions and high depths
- Extremely adherent and tight sealing
- Non-toxic and no shelf life
- For 0.6/1 kV extruded cables

90° Operating temperature

Installation temperature:
-15°C / +55°C

**Ray
tech**