




## Wonder Joint System Plus L

Straight joint with **injected gel**

Five-core spacer + screw connectors.




Product	Cable formation and conductor cross sections (n° x mm <sup>2</sup> )				Dimensions A x B (mm)
	2x	3x	4x	5x	
Wonder Joint SP L6	1,5 - 6	1,5 - 6	1,5 - 6	1,5 - 6	180 x 50
Wonder Joint SP L25	4 - 25	4 - 25	4 - 25	4 - 25	215 x 55



## Wonder Joint System Plus Y

Branch joint with **injected gel**

Five-core spacer + screw connectors.



Product	Cable formation and conductor cross sections (n° x mm <sup>2</sup> )								Dimensions A x B (mm)
	2x		3x		4x		5x		
	T	B	T	B	T	B	T	B	
Wonder Joint SP Y6	1,5 - 6	1,5 - 4	1,5 - 6	1,5 - 4	1,5 - 6	1,5 - 4	1,5 - 6	1,5 - 4	180 x 90
Wonder Joint SP Y16	4 - 16	1,5 - 4	4 - 16	1,5 - 4	4 - 16	1,5 - 4	4 - 16	1,5 - 4	220 x 105

T: Through - B: Branch

- Joints insulated with **Wonder Fluid**, single component gel
- Clean installation, re-enterable and inspectable
- Containers provided with no-return valve
- Even suitable for high depths
- Non-toxic and no shelf life
- For 0.6/1 kV extruded cables

Operating temperature **90°**

Installation temperature: **-50°C / +60°C**